


The SPARROW V3

By

ValiantGLX



← Parts A2 & B2 go on the other side.

These diagrams, in particular the motor mounts, are for use with a brushless motor. If you wish to make your Sparrow V3 brushed please use the first page of the V2.5 or V2.6 plans

- - - - = Where the Top Center Section D will sit

█ = Cut this section out for Wing Support G to slide through

